

# **John E. Thomspson P.E.**

25292 Lorin Wall Rd.  
Holden, LA 70744  
(225) 294-3061

## **Commissioning Site Visit**

**Date:** March 28, 2013

**Project:** Independence Park Main Library Baton Rouge, Louisiana

**Date Visited:** March 28, 2013

### **OBSERVATIONS**

1. Numerous conduit supports missing in the central eastern end of the building. Notified electrician on site. Approximately 10 locations were noted. Incorrect steal stud spacing caused realignment of the studs and removal of conduit clamps.
2. Other typical locations where support is need for the first floor are shown below.



**John E. Thomsson P.E.**

25292 Lorin Wall Rd.  
Holden, LA 70744  
(225) 294-3061



**Observations made by John E. Thompson P.E.**