

## FIELD REPORT

**DATE:** March 21, 2013  
**PROJECT:** Independence Park Main Library  
**WEATHER CONDITIONS:** Clear - 58°  
**SITE CONDITIONS:** Dry  
**WORKERS:** +/- 65  
**REPORTED BY:** Benjamin R. Bradford, The Library Design Collaborative

**IN ATTENDANCE:** Benjamin R. Bradford

## OBSERVATIONS:

- 1) The Monthly Owner's Meeting was held today.
- 2) The zinc wall panels on the west façade are visible.
- 3) The roofing membrane at the south green roof appears to be complete.
- 4) The zinc wall panels at the third floor continue to be installed.
- 5) The Meeting Room slab has been poured.
- 6) The following work is being installed:
  - a. Masonry
  - b. Zinc Wall Panels
  - c. Curtainwall
  - d. Exterior gypsum board sheathing
  - e. Metal studs
  - f. Air barrier
  - g. Fireproofing
  - h. Plumbing piping
  - i. Mechanical duct
  - j. Sprinkler system piping

## ATTACHMENTS:

- 1) Two (2) pages of photographs from the site visit.



