

FIELD REPORT

DATE: May 30, 2013
PROJECT: Independence Park Main Library
WEATHER CONDITIONS: Partly Cloudy - 85°
SITE CONDITIONS: Muddy
WORKERS: +/- 150
REPORTED BY: Benjamin R. Bradford, The Library Design Collaborative

IN ATTENDANCE: Benjamin R. Bradford

OBSERVATIONS:

- 1) The waterlines are being installed toward Goodwood Boulevard.
- 2) The Lobby curtainwall is being installed.
- 3) The first floor furr downs are installed.
- 4) The stretch fabric ceiling frames are on site.
- 5) Taping and floating continues.
- 6) The following work is being installed:
 - a. Zinc wall panels
 - b. Curtainwall
 - c. Exterior gypsum board sheathing
 - d. Metal studs
 - e. Air barrier
 - f. Sprinkler system piping
 - g. Interior gypsum board.

CONSTRUCTION SCHEDULE:

- 1) The Loading dock concrete pour should occur in the upcoming weeks.

ATTACHMENTS:

- 1) Two (2) pages of photographs from the site visit.



