

FIELD REPORT	
DATE: PROJECT:	November 29, 2012 Independence Park Main Library
WEATHER CONDITIONS:	Clear - 59°
SITE CONDITIONS:	Dry
Workers: Reported by:	+/- 50 Benjamin R. Bradford, The Library Design Collaborative
IN ATTENDANCE:	Benjamin R. Bradford
OBSERVATIONS:	
1)	The butterfly roofing is being installed.
2) 3)	Electrical conduits are being run to the Meeting Room. Several metal door frames have been installed.
4)	The air barrier installation has begun on the west side of the building.
5)	The structural framing for the green roof guardrails have been installed.
6) 7)	The metal decking for the meeting room and connector corridor are complete. The following work is being installed:
()	a. Exterior gypsum board sheathing
	b. Metal studs
	c. Air barrier d. Fireproofing
	e. Plumbing piping
	f. Mechanical duct
	 g. Sprinkler system piping h. Electrical conduits and junction boxes
	II. Electrical conduits and junction boxes
CONSTRUCTION SCHEDU	
1) 2)	Zinc wall panel installation is expected to start within the month. Brick installation is expected to start within the month.
,	Curtainwall installation is expected to start in the next couple of weeks.
ATTACHMENTS:	
1)	Two (2) pages of photographs from the site visit.







