

Observation Report #3

Independence Park Library

SJB Personnel: Corey Blanchard
Contractor Personnel: Milton J. Womack
Inspection Date: 7/7/14 – 4:30 p.m.
Weather Conditions: Partly Cloudy, 88°
Site Condition: Dry

Visited site to observe construction progress and inspect for scheduled concrete pour. The scheduled pour is for the entrance drive on the east side of the parking lot. All form materials, reinforcement, and base appears to be in compliance with plans and specifications.

All erosion control devices were installed and in working order. Please do not hesitate to contact this office if you have any questions or concerns.

When asked, the contractor reported no problems.

Photos





X *Corey Blanchard*

Corey Blanchard, P.E.
Project Manager, SJB Group, LLC